

SPENCER J. COX

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

Reviewed

PRIS

	Report Da	Way 18, 20	15		
Min	e Name: Lynn Springs Quarry	Permit Number:	M/003/002	5 Mine Status:	Suspended
Operator Name: Bonneville Quarries, Inc (William Bown)		Inspection Date:	05/12/201:	5 Permit Fees:	Delinquent
Insp	ector(s): Lynn Kunzler	Inspection Time:	11:30 am	Bond Amount:	\$21,700
Atte	ndee(s): Heidie Torrealday, Jeff Gabardi (USFS)	Weather:		Bond Escalation:	6/28/2013
	ection Purpose: Routine Inspection			Prior Inspection:	6/12/2014
Zennennenne	clusions and Recommendations			The inspection	
>	Elements of Inspection	Evaluated & Commented	Enforcement		
1.	Permits, Revisions, Transfer, Bonds				
2.	was not present, a note was left with an employee to pas action would be taken. As for now, no activity except re Cessation Order # MC-2015-17-05 is issued for conduct fees) Public Safety (shafts, adits, trash, signs, highwalls) Part of the activity at the site was backfilling against the the highwall. Since this is actively being abated, no enforcement.	eclamation work may ting mining operations highwall. This highw	be performed a under a suspe	until the past due fees are re ended permit (failure to remi	mitted. t annual permit
	completed, enforcement action may be taken at a later de	ate).			
3.	Protection of Drainages/Erosion Control				
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, safety)				
6.	Reclamation				
	There was a small area to the north side of the quarry that also being actively reclaimed, so inforcement action was may be taken at a later date).				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, sh	nafts)			
	Refer to comment #'s 2 and 6 above.				
8.	Soils				
9.	Revegetation				
10.	Other				

Inspector's Signature:

CC: Heidie Torrealday, USFS (htorrealday@fs.fed.us

William Bown, Operator

 $File: \ /nrwogmfs 1/OGM/GROUPS/MINERALS/WP/M003-BoxElder/M0030025-Lynnsprings/inspections/insp-05122015.pdf$

